

Renew $\frac{1}{4}$ 523/524 T255 R3W

Fl. 1943 G.L.O. BRASS Cap out of Ground
& B.T.s as follows -

ORIG 36" NOW 42" FIR S. 65° W. 48 $\frac{1}{2}$ FT.
open-face pitched over - "23" scribe
visible, alive but top broken off approx.
80° ft. up.

ORIG. 60" NOW 70" FIR N. 20° E 17 $\frac{1}{2}$ FT.
Now stump & turned out - show "24"
scribe on face. Reset BRASS cap MKD.
" $\frac{1}{4}$ 523/524 1943 " & MK. New B.T.s

14" Hemlock S. 38° W. 70 $\frac{1}{2}$ FT.
MKD. " $\frac{1}{4}$ 523 CS BT "

12" Hemlock N. 58° E, 141 $\frac{1}{2}$ FT.
MKD. " $\frac{1}{4}$ 524 CS BT "

COR. Falls on N. Edge of cat
Road course NE. & S.W. and on Edge
of Logged off unit in S. 24.

June 9, 1966

FILED

V.R.T.

J.H.

RECEIVED

JUN 9 1966

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

#13
*0

C. S. File No. 54/7-62