

Renew  $\frac{1}{4}$   $\frac{533}{54}$  T255 R7W  
T265

Ed. BT's as follows -

ORIG. 24" Now 33" Laurel S. 80°W. 18<sup>5</sup> FT.  
previously opened upper face rotted away  
we open lower & find "B" scribe & Reverse  
Ring count impossible being too close together

ORIG. 12" Now 30" Fir N. 80°W. 19<sup>2</sup> FT.  
Shows very old SCAR & Penetration SCAR  
Set 1" I.P. & BRASS Cap 2° FT. N.W.  
of fence cor. course E. & S. MKD.

"COUNTY SURVEYOR'S OFFICE 1966  
T255  $\frac{1}{4}$   $\frac{533}{54}$  T265 R7W" & MK New BT's -

14" D. Fir S. 9 $\frac{1}{2}$ °W. 27° FT.  
MKD. "  $\frac{1}{4}$  54 CS BT "

6" W. Fir N. 47°W. 33<sup>9</sup> FT.  
MKD. "  $\frac{1}{4}$  533 CS BT "

Cor. lies approx. 100 FT. W. of small  
DRW course S.E.

June 14, 1966

FILED  
RECEIVED  
V. R. M.  
T. B.  
J. H.

JUN 14 1966

*[Handwritten signature]*

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

481-T26-1  
X#PA O

C. S. File No. 54/10-6