

510/511

Renew Sec. Cor. 515/514 T23S R9W

Fd. one BT. as follows -

Orig. 18" <sup>Hemlock</sup> Now 46" S. 51° W. 20.5 ft.

Previously opened many years ago or never completely healed over, shows "3 9W 15 T" scribe on badly rotted face

No trace other Orig. BTs - set 1" I.P.

& Brass cap MKd. "COUNTY SURVEYORS

OFFICE 1967 T23S <sup>510/511</sup>/<sub>515/514</sub> R9W"

& MK. New BTs -

46" Hemlock S. 51° W. 20.5 ft.

Rescribed "T23S R9W S 15 CS BT"

5" Hemlock S. 65° E. 13.5 ft.

Mkd. "S 14 CS BT"

28" Hemlock N. 53° E. 35.5 ft.

Mkd. "T23S R9W S 11 CS BT"

No suitable tree in Sec. 10 - This cor. lies approx. 135 ft W. of other creek course N.E.

Jan 4, 1967

FILED RECEIVED

U.R.T.  
J.H.  
D.W.

JAN 4 1967

*[Handwritten signature]*

COUNTY SURVEYOR DOUGLAS COUNTY, ORE.

at 23  
X

CO. K.

J. W. B. C. S. File No. 54/1254