

Renew <sup>516/515</sup> 521/522 T235 R8W

Ed. O.B.T.'s as follows -

Orig. 28" Now 34" Fir N, 35° E, 4 6 ft.

Now SN29 - shows "T2 S R 8 W

515 BT" Bark scribe in poor cond.

Orig. 40" Now 44" Fir S, 66° E, 12 5 ft.

Now SN29 - shows SCAR - do not open.

Orig. 8" Now 24" Fir N, 77° W, 23 1 ft.

alive - shows faint SCAR - we Rescribe

"T235 R8W 516CS BT" - find large

hole where SW BT. once stood.

Set 1" I.P. & Brass Cap MKd "COUNTY

SURVEYOR'S OFFICE 1967 T235

<sup>516/515</sup> 521/522 R8W" & MK. New BTs -

10" D. Fir S, 70° W, 16 7 ft.

Mkd. "T235 R8W 521CS BT"

6" D. Fir S, 20° W, 19 3 ft.

Mkd. T235 R8W 521CS BT"

5" W. Fir N, 49° E, 22 8 ft.

Mkd. "515CS BT" No suitable

Tree to S.E. Cor. Lies on steep

South slope approx 4 chns. North  
of Mehl creek.

Feb 24, 1967

VR.T.

J.H.

D.W.

*R. J. Raley*  
\* C.S. File No. 5412 -32 J. x. 1. 8.