

Renew  $\frac{1}{4}$  516  $\frac{1}{4}$  515 T235 R8W

Fd. Remains of one BT. as follows -

Orig. 9" D. Fir S. 44° W. 13 $\frac{3}{4}$  ft.

now Rotted Stump - unhealed face shows " $\frac{1}{4}$  S"

scribe. NO TRce S.E. Orig. BT.

set 1" I.P. & Brass Cap MKd. "COUNTY

SURVEYOR'S OFFICE 1966 T235  $\frac{1}{4}$  516  $\frac{1}{4}$  515

R8W" & MK. New BTs.

20" D. Fir S. 88° W. 22 $\frac{3}{4}$  ft.

Mkd. " $\frac{1}{4}$  S 16 CS BT"

22" I. Cedar N. 80° E. 31 $\frac{0}{4}$  ft.

Mkd. " $\frac{1}{4}$  S 15 CS BT"

This cor. lies on steep S. slope

approx. 300 ft south of top of Ridge

course E. & W.

April 21, 1966

U.R.T.  
M.S.  
J.H.

U.R.T. Tracy

FILED

RECEIVED

APR 21 1966

COUNTY SURVEYOR

DOUGLAS COUNTY, ORE.

C. S. File No. 54/12-39

\*38  
OK