

Renew Sec. Cor. $\frac{56}{57} \frac{55}{58}$ T235 R8W

Fd. 4W Recorded $\frac{1}{2}$ " I.P. with cast Iron
Cap Brazed on top & MKd. $\frac{56}{57} \frac{55}{58}$ " &

BT's as follows -

ORIG. 50" FIR N. 1° E. 14⁵ ft. (face)
find old axe mk. in Remains of Bark at
Base of Bad decayed stump.

ORIG. 24" FIR S. 31° W. 19⁸ ft. (To hole)
Remains of Turned out Tree - No scribe fd.

ORIG. 24" Now 30" FIR N. 79° W. 31⁷ ft. (face)
Now Badly Decayed Stump - find "BT"

BARK scribe in very poor cond. at Base
of Stump. - No Trace of BT. To S.E.
We do not set BRASS cap. We mark
New BT's -

17" R. Cedar N. 45° E. 17⁹ ft.
MKd. T235 R8W 55 CS BT"

13" D. FIR N. 56° W. 17³ ft.
MKd. T235 R8W 56 CS BT"

17" Hemlock S. 11° W. 13⁸ ft.
MKd. T235 R8W 57 CS BT"

14" D. FIR S. 75° E. 15⁰ ft.
MKd. T235 R8W 58 CS BT"

COR. Lies approx 100ft. S. of Road
course E-W.

Dec 9, 1966
* #41

[Signature]
U.R.T.
J.H.
C.S. No. 57/72-46