

Renew $\frac{1}{4}$ W $\frac{1}{2}$ S 6 only T235 R8W

Fd. B.T.s 25 follows -

orig. 8" now approx. 12" Hemlock N. 45° W, 17 $\frac{8}{8}$ ft

Now very badly decayed STAB - we open &

find "BT" Reverse scribe & find $\frac{1}{4}$ "

Reverse scribe in decayed log on ground

orig. 20" now 34" Fir S. 1° E. 17 $\frac{8}{8}$ ft,

Not S. 10° E. 25 Recorded. - 2 live &

shows scars - do not open. at Bearing;

From Hemlock & intersection of distances

Set 1" I.P. & Brass cap MKd. "COUNTY

SURVEYOR'S OFFICE 1967

T235 R9W $\frac{1}{4}$ S 6 R8W " & MK. New

B.T.s -

" 9 Hemlock N. $74\frac{1}{2}^{\circ}$ E. 10 $\frac{8}{8}$ ft.

Mkd. $\frac{1}{4}$ S 6 CS BT"

" 14 Hemlock N. 47° E. 19 $\frac{8}{8}$ ft.

Mkd. $\frac{1}{4}$ S 6 CS BT"

This cor. lies on Top of small

SPUR Ridge course N.W. 219° $21\frac{1}{2}^{\circ}$

I.P. Bears N. 71° W. 3 $\frac{9}{8}$ ft. (unrecorded)

FILED

Feb. 20, 1966

RECEIVED

H.P.T.
V.H.
D.W.

FEB 20 1967

[Handwritten signature]
7-0-R9W
381-28W

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

C. S. File No. 55-12-63 O.R. J.W.B.