

Renewal # 29

18/17  
19/20

T233 RBW

orig. Hemlock Now 10' stump N22 W 31<sup>2</sup>  
Faint scribe visible "518"  
20" Hemlock Now 7' stump S76 E 19<sup>5</sup>  
Scribe visible T233 RBW S20 CD BT

20" Cedar uprooted stump lying on face  
(K BT) BT Tag)

No trace of 1965 Brass cap Area Andly  
Zero up from logging.  
other BTs destroyed

Renewal

Set Brass cap at Sec cor MKD.  
county Surveyors office

T233 RBW

518 1317  
519 520

1972

Also steel Fence Post along side

Note: This cor lies in old clear cut -  
No trace available for BTs

I do Tag a 50" Fir stump S 79 W 45<sup>5</sup>

Also 30" cedar stump S37 E 43<sup>2</sup>

8-3-72

*[Signature]*

#1000 ✓

C. S. File No. 54/12-70 D.K. JRL

DIETZGEN NO. 385-6