

Renew $\frac{1}{4}$ $\frac{517}{520}$ T215 R5W

Fd. Haines "T" IRON 25 Recorded in
Renewal #77 & BT's 25 Follows -
Orig. 20" Now 50" FIR N. 30° E. 35 $\frac{1}{2}$ ft.
shows "BT $\frac{1}{4}$ S" BARK SCRIBE appears
to be very old - This BT has another tree
Leaving into it.

Orig. 36" Now 58" FIR S. 64° E. 13 $\frac{1}{2}$ ft.
Fd. possible BARK SCRIBE - this B.T.
injured & BARK IS BURNED - Because of
The size & condition of orig BT's,
we MK. New BT's -

8" D. FIR S. 80° E. 32 $\frac{1}{2}$ ft.
MKd. " $\frac{1}{4}$ 520 CS BT "
15" D. FIR N. 28° W. 28 $\frac{1}{2}$ ft.
MKd. " $\frac{1}{4}$ 517 CS BT "

This COR LIES ON N. Side of RUINE
Course N. 70° W.

Sept 13, 1965

U.R.T.
M.S.
T.C.
FILED
RECEIVED

SEP 13 1965

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

C. S. File No. 54/14-13

~~1/20~~
FX