

Renew NE Township Cor T215 R5W

Fd. old 3/4" I.P. 19" Long & Broken Stone

20" x 9" x 6" MKd. "20 R5 536" Firmley

Set A BT's as follows -

ORIG. 8" Now 23" R.F.I.R (STUMP) N. 50° W. 5 3/4 Ft.

open & find " T R5 BT" scribe & Reverse.

ORIG. 8" Now 26" R.F.I.R (STUMP) N. 75° E. 6 1/2 Ft

No scribe fd.

8" Now 14" R.F.I.R (STUMP) S. 15° W. 5 3/4 Ft

find Reverse " B" scribe. No Trace S.E.

BT, all BT's Badly Rotted. Measurements

Taken from face. Set 1" I.P. & Brass cap

at cor. point MKd" Doug. Co. SURVEYOR'S

OFFICE, 1965 T205 T215 R4W R5W

536 | 531"

51 | 56" & MK. New BT's -

7" D.I.F.I.R S. 46° W. 4 1/2 Ft

Mkd. " T215 R5W 51 DCS BT"

8" D.I.F.I.R N. 4° W. 7° Ft,

Mkd. " T205 R5W 536 DCS BT"

7" D. F.I.R East 17 3/4 Ft.

Mkd. " T205 R4W 531 DCS BT"

8" D. F.I.R S. 21° E. 23 3/4 Ft,

Mkd. " T215 R4W 56 DCS BT"

Sept 8, 1965

V.R.T.

M.S.

T.C.

*[Handwritten signature]*