

T215536 | 531 R6W

Renew Township COR. of R7W51 | 56 T22S

Ed. Haines "T" IRON 75 Recorded
in Rev. #43521-6 under a 16" Log
Set from orig. BT as follows -

orig. 20" Now 28" Fir N. 59° E. 37 6 ft,
we open & find, " 31 T21 SW " scribe

Now SN 27. All other B.T.s are
are destroyed, set 1" I.P. & BRASS

cap 6" South of "T" IRON alongside of
Log. MKd. COUNTY SURVEYORS OFFICE

1966 T215 R7W 536/531
51 | 56 T22S R6W " & MK.

New B.T.s -

7" Hemlock N. 26 °W. 13 2 ft,

Mkd. " T215 R7W 536 CS BT "

9" Hemlock N. 80 °E. 24 7 ft,

Mkd. " T215 R6W 531 CS BT "

26" R. Cedar S. 61 °E. 29 7 ft,

Mkd. " T225 R6W 56 CS BT "

No suitable Tree close to SW.
COR. Lies on steep N.W. Slope.

FILED

Sept. 1, 1966

RECEIVED

#115-721-6
#25-721-7
#24-722-6
#22-722-7

J.B.
J.H.

SEP 1 1966

[Handwritten Signature]

COUNTY SURVEYOR

DOUGLAS COUNTY, ORE.

C.S. File No. 54/14-20

#