

Renew Sec. Cor. $\frac{54}{59} | \frac{53}{510}$ T215 R4W

Fd. old charred ~~wood~~ wood Post
FOR. COR. & B.T.S follows - See Ren. #4

Orig. 8" Now 24" cedar N. 68° W. 2° ft.

Burned stump - "BT" scribe visible on open
Blaze.

Orig. 10" Now 48" Fir S. 12° W. 24 1/2 ft.

Now 5 1/2" - Injured - hollow - No scribe Fd.

No Trace other Orig. B.T.S -

coles' 24" Now 28" W. Fir N. 54° E. 59 1/2 ft.

Now Sawn Stump - old AXE MKS - No scribe

coles' 18" Now 24" Fir S. 20° E. 46 1/2 ft.

Sawn stump - too Low for scribe

No Trace coles other B.T.S - at cor.

point set 1" I.P. & BRASS cap MKd.

"COUNTY SURVEYORS OFFICE 1969

T215 $\frac{54}{59} | \frac{53}{510}$ R4W" & MK. New B.T.S -

8" D. Fir. N. 84° E. 37 1/2 ft.

Mkd. "T215 R4W 53 CS BT"

8" chingapin S. 60° W. 22° ft.

Mkd. "T215 R4W 59 CS BT"

8" chingapin N. 54° W. 30 1/4 ft.

Mkd. "T215 R4W 54 CS. BT" No suitable

Tree in sec 10.

April 3, 1969

#109 R. Tracy

C. S. File No.

V.R.T.
J.G.H.
V.O.P.

54/14-22

O.H.
J.W.O.