

Review $\frac{1}{4}$ COR. 54 | 53 T215 R4W

Fd. Mound of stone & B.T.s 25

Recorded in Ren. # 6 25 follows -

ORIG. 8" Now 24" cedar N. 47° W. 23 $\frac{1}{2}$ ft.

Dead & Burned out - Find probable
bottom of old blaze - No scribe.

coles 24" Now 28" Fir S. 18° E. 23 $\frac{1}{2}$ ft.

Now Badly decayed Remains of stump.

No scribe Fd. - we do not find any

Trace of cedar post called for. at

COR. point set 1" IR & BRASS

cap MKd. "COUNTY SURVEYORS

OFFICE 1969 T215 $\frac{1}{4}$ 54 | 53

R4W" & MK. New B.T.s -

9" D. Fir. S. 55° W. 12 $\frac{1}{2}$ ft.

Mkd. " $\frac{1}{4}$ 54 CS BT"

9" D. Fir N. 11° E. 15 $\frac{1}{2}$ ft.

Mkd. " $\frac{1}{4}$ 53 CS BT"

2 Steel fence post bears

N. 28° E. 7 $\frac{1}{2}$ ft. - Mkd. "Approx

$\frac{1}{4}$ COR. " Reset Rock Mound

around BRASS cap. This COR.

Lies on nearly flat E. slope

in Dense Brush & Reprod.

April 3, 1969

#110, R. Tracy

V.R.T. J.G.H. V.D.P. ^{o.k.} _{1/27}

C. S. File No. 34/143 27