

Renew $\frac{1}{4}$ cor. 518 / 517 T215 R4W

Fd. O.B.T.s as follows -

Orig. 8" Now 22" Fir N.60°W 27 $\frac{1}{2}$ ft.

Down & Badly decayed - we open & find
scribe mks "A S B /" This B.T. was
chopped open many years ago.

Orig. 9" Now 24" cedar (Redwood) S.48°E. 17 $\frac{3}{8}$ ft.

Now snag - we open & find " $\frac{1}{4}$ S T"

Rescribe under 50 years overgrowth
opening deeper we find center decayed
& overgrowth curled around inside.

2nd cor. point set 1" IR & Brass cap
mkd. "COUNTY SURVEYORS OFFICE

1969 T215 $\frac{1}{4}$ 517 / 518 R4W" &

Mk. New B.T.s -

9" Hemlock S. 23°W. 14 $\frac{1}{4}$ ft.

Mkd. " $\frac{1}{4}$ 518 CS BT"

10" Hemlock S. 18°E. 9 $\frac{1}{2}$ ft.

Mkd. " $\frac{1}{4}$ 517 CS BT"

This cor. lies dry gully - we
do not find creek 2' ^{cks} wide

course East at 41.00 chns as

called for in field notes.

April 11, 1969

~~1061~~ R. Tracy

V.R.T.

J.G.H.

V.D.P.

C.S. File No. 5414-30

D.K.
J.W.B.