

Review  $\frac{1}{4}$   $\frac{531}{56}$  T205 R4W Douglas Co. 43 NE

Fd. Very old  $\frac{3}{4}$ " I.P. at COR. point  
UNRECORDED & O.B.T.S 25 follows -

ORIG. 30" NOW 60" FIR N. 61° W. 81 ± FT.

NOW STUMP - find, " T " BARK scribe

ORIG. 28" NOW 40" FIR S. 7½° W. 56 ± FT.

NOW SNAG - PREVIOUSLY CHOPPED OPEN

Decayed - NO scribe - Weyerhaeuser  
Method B.T.S. (see CS, 53-103)

26" D. FIR N. 18° W. 13 ± FT.

" W " NOIL & BRASS DISC. at Base.

65" D. FIR S. 36° W. 51 ± FT.

BRASS disc Barely visible at Base  
at COR. point in place of old I.P. set

1" I.P. & BRASS cap MKd. " Doug. Co.

SURVEYOR'S OFFICE 1968 T205

$\frac{1}{4}$   $\frac{531}{56}$  T215 R4W " & MK. New B.T.S.

17" D. FIR N. 35° W. 16 ± FT.

Mkd. " $\frac{1}{4}$  531 DC5 BT"

12" D. FIR S. 54½° W. 55 ± FT.

Mkd. " $\frac{1}{4}$  56 DC5 BT" Reset I.P. along  
side BRASS cap - COR. Lies at fence

COR. - Fences N. & E.

Dec. 26, 1968

VRT  
FWP  
V.P.

~~Q. R. Tracy~~  
\*98

O.V.  
E.W. 19.

E.S. File No. 59/14-39