

Renew Sec. Cor. $\frac{518}{519} | \frac{517}{520}$ T215 R4W

Fd. $\frac{3}{4}$ " shaft, 2^d fence cor. & B.T.S
25 Recorded in Ren. #31-

6" Now 15" R.F.I.R S. 65° E. 17⁸ ft
2 live - healed Blazze.

10" Now 18" R.F.I.R N. 84° E. 27° ft
2 live - we Rescribe "T215 R4W S 17CS BT"
over old SCOR.

18" Now 24" Double Laurel N. 71° W. 119° ft
2 live - scribe MKs visible on nearly
healed Blazze. 2^d cor. point in
place of $\frac{3}{4}$ " shaft set 1" I.P. &
BRASS cap MKd. "COUNTY

SURVEYOR'S OFFICE 1968 T215

$\frac{518}{519} | \frac{517}{520}$ R4W " & MK. New BT.

10" D. F.I.R S. 44° W. 52° ft
MKd. "T215 R4W S 19CS BT"

Reset shaft alongside BRASS
cap. fences N.-S. - E. & W.

Dec. 30, 1968

U.P.T.
FWJ
U.P.

V.R. Tracy

0
99

O.K. J. W. B.

C.S. File No. 54/14-40