

38/52  
Renew Sec. Cor.  $\frac{510}{511}$  T215 R4W

Fd. Very old 4" x 4" x 48" cedar post at

Cor. - No marks & O.B.T.s as follows -

Orig. 70" Now 72" Fir N. 30° W. 5 1/2 ft.

Now Sawn stump - No scribe Fd.

Orig. 10" Now 32" Fir S. 70° E. 28 1/4 ft.

Turned out - we open & find "SN T215"

scribe. Find hole where orig

NE. B.T. would have been - No

Trace S.W. O.B.T. - at cor. Point

set 1" I.P. & Brass cap MKd "COUNTY

SURVEYORS OFFICE 1969 T215

$\frac{53}{510}$  R4W " & MK. New B.T.s -

10" R. Fir S. 22° W. 19 3/4 ft.

Mkd "T215 R4W S10 CS BT"

7" D. Fir S. 30 1/2° E. 17 1/2 ft.

Mkd. "T215 R4W S11 CS BT"

5" D. Fir N. 83° W. 11 1/2 ft.

Mkd. "S3 CS BT"

18" I. cedar N. 55° E. 54 1/2 ft.

Mkd. "T215 R4W S2 CS BT"

This cor. lies on moderate S.E.

Slope in dense brush

Jan. 2, 1969

U.R.T.

F.W.J.

V.R.

C.S. File No. 54/14-46

O.K.  
J.W.D.