

Renew  $\frac{1}{4}$  COR.  $\frac{518}{519}$  T21S R5W

Fd. stump of O.B.T. 25 follows -  
ORIG. 10" Now 30" Fir N. 32° E. 23  $\frac{1}{2}$  ft.

Now sowed stump - Badly decayed  
partial scribe mks. "B" Fd.

at a point for other O.B.T. - There  
is a hole - No trace of tree

& No trace of cor. stone Fd. - at

cor. point set. 1" I.P. & Brass cap

MKd. COUNTY SURVEYORS OFFICE

1970 T21S  $\frac{1}{4}$   $\frac{518}{519}$  R5W" - MK. New B.T.s -

24" cedar S. 66° W. 53  $\frac{1}{2}$  ft.

MKd. " $\frac{1}{4}$  519 CS BT"

12" cedar N. 26° W. 26  $\frac{1}{2}$  ft.

MKd. " $\frac{1}{4}$  518 CS BT"

From cor. point a 40" cedar bears  
S. 39° W. 21  $\frac{1}{2}$  ft. - has been chopped

open over 100 rings - Nothing Fd.

This cor. lies on N. E. slope

50 ft. South & 75 ft. West of DRY

Ravine course S.E. - in dense undergrowth -

Note - See also C.S. 41-35

July 30, 1970

V.R.T.  
V.D.P.

6 1/2' - 9'  
1/3'

V.B. Tracy

#139

C.S. File No. 54/14-50