

Renew Sec. COR. R4W  $\frac{513}{574}$  |  $\frac{518}{519}$  R3W LANE Co. T235

Fd. orig. 6" Now 8" Vine maple cor. Tree  
BARK scribe "T235 R4W" on S.W. side

other scribe fragmentary - only BT's  
Now stumps with only S.E. in position

orig. 30" Now 44" Fir (stump) S. 65° E, 21<sup>8</sup> ft.  
shows "5" BARK scribe.

Weyerhaeuser BT's Recorded in Ren. # 98

Now stumps except SW, -

17" Hemlock S. 34° W, 32<sup>7</sup> ft.

"W" nail & plate. Not scribed.

Creek colls out of cor. fit reasonably

well. COR. Tree in very poor

cond. - we tip out & set 1" I.P.

BRASS cap MKd. "Doug. COUNTY SURVEYORS

OFFICE 1965 T235 R4W  $\frac{513}{524}$  |  $\frac{518}{519}$

R3W " in its place & MK. New BT's -

15" Hemlock S. 5° E, 40<sup>6</sup> ft.

Mkd. "T235 R3W S 19 DCS BT"

9" Hemlock S. 67° W, 17<sup>9</sup> ft.

Mkd. "T235 R4W S 24 DCS BT"

13" Hemlock N. 68° E, 43<sup>3</sup> ft.

Mkd. "T235 R3W S 18 DCS BT"

No Tree suitable To N.W. -

Nov. 19, 1965

V.R.T.

M.S.

J.L.

~~TX #139~~  
*[Signature]*  
#26 252 23-4

C.S. File No. 54/16-22