

Renew Sec. COR. $\frac{2}{11} \frac{1}{12}$ T235 R4W

Fd 3 BTs Recorded in Renewal #44

25 follows -

32" D.FIR S. 69° E. 15.1 ft To face

Shows SCARS - we do not open. alive.

22" D.FIR S. 50° W. 41.5 ft To face

Shows SCARS & "W" Nail - alive

36" D.FIR N. 79° W. 8.7 ft To face

Shows SCAR & "W" Nail - alive - wire

fence attached to N. side.

N.E. BT, now shattered stump. We

set 1" IP & BRASS cap MKd "COUNTY

SURVEYOR'S OFFICE 1965 T235

$\frac{52}{51}$ / $\frac{51}{52}$ R4W " & MK New BT -

21" R. cedar N. 55° E. 175 ft. (center)

Mkd "T235 R4W S1 CS BT"

This COR. lies 2° ft S. of

Fence Bearing S. 78° E.

Nov. 5, 1965 FILED

V.R.T.

RECEIVED

MS.

J.L.

NOV 5 1965

W. R. Tracy

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

16
3125
+X

C. S. File No. 54/16-38