

520 | 521
529 | 528

Renew Sec. Con. T235 R4W

Fd. 3" square cedar post Burned off at ground

level - scribes " 21. 528 529 520" & Boyers

BTs as Recorded in Ren. #15 & Orig B.T. as follows

Orig 10" Now 17" W Oak N. 18 3/4° W. 576 7 ft.

Previously opened & shows " 235 R4W 2" scribe.

2 live-face Rotting. Boyers BTs -

36" Now 39" I. Cedar N. 14° E. 85 3 ft (slope)

Scribe visible " 521. T235 R4W " 2 live.

20" Now 36" Forked Ash S. 54° E. 290 3 ft. (slope)

15 shows faint scar - Lies in Blackberry Bush

12" Now 32" I. cedar S. 81 1/2° W. 205 3 ft. (slope)

Rescribed by Cad. Eng.'s " T235 R4W 529 BT "

we set 1" IP. & Brass Cap (in N-S. fence) MKd.

" COUNTY SURVEYOR'S OFFICE 1966

T235 ^{520 | 521} _{529 | 528} R4W " when digging for BRASS

cap, we find Remnants of cedar post, MK.

New B.T. -

9" I. cedar N. 40° W. 40 2 ft.

Mkd. " T235 R4W 520 CS BT "

Cad. Brass cap Bears N. 57 1/2° W. 31 5 ft.

(To be Removed in future)

Sept 26, 1966

V.R.T.
J.H.

142
* [Signature]