

530 | 529  
Renew Sec. CoR. 531 | 532 T235 R3W

Fd. O.B.T.s 25 follows -

Orig. 28" Now 53" Cedar N. 40° E, 29 1/2 ft.

Now STump - Reverse face & AXE Notch  
visible on Top of STump.

(Possible)  
Orig. 6" Now 18" Hemlock S. 49° E, 22 1/2 ft.

2 live - No scar showing - we scribe

"T235 R3W 532 CS BT" (Record S. 55° E.)

Orig. 40" Now 50" Hemlock S. 3° W, 42 1/2 ft.

Now STump - "531" visible we open Lower  
& find "BT" scribe.

Orig. 30" Now 42" Hemlock N. 25° W, 26 1/2 ft.

Now STump - shows SCAR - set 1" I.P.

& BRASS cap MKd. "COUNTY SURVEYORS

OFFICE 1967 T235 531 | 532 R3W" &

set 6 1/2" steel fence post along side BRASS CAP -  
Ren. # 23 B.T.s 25 follows -

32" cedar S. 32° E, 65 1/2 ft.

(Not S. 28° W.) "532 BT" Now STump

20" cedar N. 27° E, 81 1/2 ft.

"529 BT" (Not 80 1/2 ft)

GARDINERS NW. B.T. gone completely

& S.W. B.T. Down N. This CoR. lies

on East slope approx 150 ft. W.

of small Ruine course N.

Nov. 8, 1967

U.R.T.

#56 O. N. R. Tray

D.H.

C.S. FILE NO. 54/16-52