

Revised  $\frac{527}{334} \frac{526}{535}$  73/5 R4W

Found:  
Iron P. Pe #1 sec cor. - Cor. #10  
WENDOTA'S

26" Fir now 28" N62W 232  
good Scar

14" Fir now 19" N75E 257  
Face Rotten

15" Cedar now 17" S40E 231  
good Scar

10" Fir now 14" N55E 262  
good Scar: I find this bearing to be  
N51E

9" Fir now 15" S81E 294  
good Scar

8" Cedar now 19" S26W 342  
Scribe visible "5" "39"  
I find this bearing to be S62W

Revised:  
Along Iron P. Pe set Cross  
Cap of Sec cor MTD,  
county Surveyors office  
73/5 R4W

$\frac{527}{334} \frac{526}{535}$   
1966

All Bearing trees in good shape,

2-8-66

*[Signature]*  
J.C.B.

\*#116

C. S. File No. 54/20-16

DIETZEN NO. 385-6