

Renewed)

~~S35~~ S36

T31S R4W

Found:

CBTS

6" B. Oak N 10 1/2° W 29' 2"

Tree very rotten scribe visible

" 5"

10" B. oak N 10 1/2° E 13' 2"

opened for scribe 13' 2"

Center of tree rotted out

No trace of cor. stone.

Renewed:

Set Brass cap at $\frac{1}{4}$ cor MAR.
county Surveyors office

T31S R4W

$\frac{1}{4}$ S35/S36

1966

DIETZGEN NO. 385-6

New Bearing Trees

5" Pine West 32' 1/2"
Scribed: $\frac{1}{4}$ S CS RT

9" Pine N 46° E 19' 1/2"
Scribed $\frac{1}{4}$ S 36 CS RT

3-9-66

JWG

JCB

JWG

*0 #127-

C. S. File No. 54/20-129