

Renewal

S 32  
SS-

T 31 S R 3 W  
T 32 S R 4 W

Found:

Iron pipe at  $\frac{1}{4}$  cor. - BE RM 1-37

5" Oak Nawl 8" S 30 E 7 9  
Scribe visible  $\frac{1}{4}$  S'

I find this bearing to be S 53 E

10' Pine Nawl 12" N 59  $\frac{1}{2}$  W 19 1  
Tree had been opened & flaked over  
I find this bearing to be N 66 W

I set this cor by Iron P.P.  
& 2 correct distances.

Renewed:

Alongside Iron P.P.

Set Brass cap at  $\frac{1}{4}$  cor N 82

County Surveyors office

T 31 S

A S 32 R  
1 30 1  
W

T 32 S

1916

New Bearing trees

14" D Fir N 25 W 26 0  
Scribed  $\frac{1}{4}$  S 32 S S 87

15" Pine S 41 W 46 6  
Scribed  $\frac{1}{4}$  S 5 S S 87

2-10-66

J. M. G.  
S. C. G.  
S. W. G.

\* #120  
593-732

U. S. File No. 54/20-31