

Renewed

535/536
52/51

T315 R4W
T325 R4W

Found
R4W OBT

24" Fir Now 21" N 32° 10' E 30 3/4
Shows good Scar

6" Laurel Now 19" N 24° 31' W 20 1/4
Scribe Visible "B"

19" Fir Now 17" S 30° 50' W 13 E
Has been opened no scribe visible

10" Laurel S 5° 45' E 8 1/2

This Tree very Rotten
Iron Pipe at Cor.

Renewed BT

14" Fir Down N S 25° E 22 1/2

Renewed:

Along Side Iron Pipe
Set Brass cap at Sec. Cor. MAD.
County Surveyors office

T315 R4W
535/536
52/51
T325
1966

Relayed & Rescribed

19" Laurel N 24° 5' W 20 1/4
Scribed T315 R4W S 25° CS BT

New Bearing Trees:

8" Fir S 46° W 10 3/4
Scribed T325 R4W S 2 CS BT

8" Laurel S 27° E 29 1/2
Scribed T325 R4W S 1 CS BT

Renewed # 8

2-18-66
[Signature]

* #121
#99-732

C. S. File No. 54/20-32

DIETZGEN NO. 385-6