

Renewal 512/57 T-315 1746

Found:

6" Fir DOWN S 84 E 42°

2" D. Fir Now 8" S 75 E 35°
Shows good Scar

12" D. Fir Now 15" N 29 W 31°
It is visible

O.B.T. 1st cor had been opened
for service. $\frac{1}{2}$ on W. Face

OBT 28" D. Fir N 19 E 40°

No Trace of Iron pipe at
cor.

Renewed:

Set Brass cap at $\frac{1}{2}$ cor 1746,
County Surveyors office

T-315
R 512/57 R
W W
1946

FB Noted Ad. Bears North
1946

2-28-66
[Signature]

Renewed #90

* J.B. #123
5126-RW

U.S. File No. 54/20-37

DIETZGEN NO. 3885-6