

Revised

530
536

T315 RAW

Found:

10" Fir Now 18" N67W 23°
Tree had been opened for strike
15' visible

12" Fir S18W 5°
No trace of this tree.

Revised:

Set Brass cap at $\frac{1}{4}$ sec. cor ~~Map~~
County Surveyors office.

T315 RAW

$\frac{1}{4}$ $\frac{535}{536}$

1966

DIETZGEN NO. 385-5

This cor lies on south slope of ridge
bearing about E+W. Also about
50' E+W north of small drain. It is
now on edge of cut unit.

New Bearing Trees

22" D. Fir N112E 31°
Scribed: $\frac{1}{4}$ 535 cor BT

7" Cedar S61W 25°
scribed: $\frac{1}{4}$ 536 cor BT

1-27-66

*146

O.K. J.W.B.

C.S. File No.

54/20-44