

Renewal

59/510
516/515

T315 RAW

Found:

Iron Pipe end Stone with Notches
Can # 23

50" Fir NW 50" S57W 118
Shows good scar.

12" Fir N 77 1/2 W 46 2
This tree down & rotten

12" Fir NW 18" N46E 23 9
Shows good scar

No Trace of Laurel Bearing Tree

Renewal:

Along side Iron Pipe
Set Brass cap at Sec cor MKD,
county surveyors office

T315 RAW

59/510
516/515

1916

DIETZGEN NO. 385-6

New Bearing Tree

23" Cedar S 49 E 172
Scribed T315 RAW 515 C.S. BT

Be Blazed & Be scribed

10" D. Fir N 66 E 239
Scribed T315 RAW 510 C.S. BT

4-28-66

J.W.B.
C.S.
1916

* #148

J.W.B.

C.S. File No. 54/20-46