

Renewed

530
525 331
536

T313 R45W

Found:

36" Fir Now Dead Snag N74E 78[±]
Shows Scar.

20" Fir Now Flaw Down S81[±]E 40[±]

33" Fir Now Stump S39[±]W 19[±]
Scribe Visible "5" "3"

No Trace of Stone at cor.

Renewed:

Set Brass cap at sec cor. M.D.
County Surveyors office

T313

R	530	R
S	525	T
W	531	W

1966

New Bearing Tree

3" Fir Scribed S30 BT N79[±]E 19[±]

Reblazed & Rescribed

39" Fir Stump S39[±]W 19[±]
Scribed T313 R5W S25[±] BT

This cor lies in large cut unit.

1-21-66
JWB
FCB

* O #150
#66-R5W
O.K. J.W.B. C.S. No. 54/20-40