

Revised

519  
530  
S29  
S25

T315 R1 E SW

Found:

8" D. Fir Now Down rotten N60W 73  
opened for Scribe "315" "B"

12" D. Fir Now Stump S68W 27+

10" D. Fir Now 13" S10E 41E  
Shax's good clear.

No Trace of Stone at cor.

Revised:

Set Brass cap at sec cor MKD,  
County Surveyors office

T315  
R  
S S29 S30 A  
W S25 W

1966

New Bearing Trees:

29" D. Fir N5E 154

Scribed T315 R4W S30 CS BT

10" D. Fir S29W 45

Scribed T315 R3W S25 CS BT

This cor lies on the west edge of River  
line R/W

A-22-66  
JWB

D.W. J.W.B.

\* O #152 - 4W  
#68 - RSW

C. S. File No. 54/20-50

DIETZGEN NO. 385-6