


Section 27 Twp 20 S Rge 6 W Date: 4-4-72



How was corner identified? US GLO BRASS CAP 1950

2 BT'S TAGGED - 2 POSSIBLE NOT TAGGED

(EAST)
Condition of corner: GOOD - CORNER WAS ON UPPER EDGE OF

ROCKED ROAD CUT BANK WHICH DROPPED OUT. CORNER
LYING ALONG EDGE OF ROAD (EAST SIDE)

Best route to reach corner: FROM SMITH RIVER COUNTY ROAD - UP
BLM ELK CREEK ROAD 20-6-32, 20-6-24, 1 TO PUT ROCKED
SPOT ABOVE REC. 23 TO NE COR

Quadrant	NE	NW	SE	SW
Species & Size	DF 36"		DF 18"	
Dist. & Bearing	N 49 E 33 FT.		E - 35 FT	
Condition of Seal	GROWN OUT		GROWN OVER	BANK USABLE
Original or Resurvey	BANK USABLE 41			
Appearance of B.T.				
Tags, Marks, etc.	BLM BT WTCO POST		BLM BT - 1965 WTCO TAG	

Other Remarks:

We Reset G.L.O.B.C.
IN PLACE ON
ROCK BANK

C.S. File No. 54/22

Bary Williams
Signed
RS186 BLM

Postage
Will be Paid
by
Addressee

ROSEBURG, OREGON
APR 4
1972
9 7 A 70

BUSINESS REPLY CARD
PERMIT NO. 102 ROSEBURG, OREGON

U.S. POSTAGE
08
ROSEBURG, OREGON
APR 5 1972
METER
FD.167353

we need
DOUGLAS COUNTY SURVEY
B.C.
ROOM 122, COURTHOUSE
No New
ROSEBURG, OREGON
ETS

FACE
OF

