

FOUND COR.

531 T269 R7W  
56 T275 R7W

FOUND 1/2" I.P. & Weyerhaeuser

BT. "W" Nail Method as follows-

58" D. FIR N. 60° E. 36° FT.

"W" Nail under tag.

49" D. FIR S. 77° E. 36° FT.

"W" Nail under tag.

We find no orig scribe on

either BT. or Record of this Renewal.

MARCH 17, 1966

U.R.T.  
J.H.

*[Handwritten signature]*

Not Found Corners on Reverse Side.

FILED  
RECEIVED

MAR 17 1966

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

C. S. File No. 54/23-1

RAY



**Weyerhaeuser Company**

Wood Products Division

Coos Bay Branch  
North Bend, Oregon 97459

March 29, 1966

Mr. L. Lewis  
Douglas County Surveyor's Office  
Douglas County Building  
Roseburg, Oregon

Dear Mr. Lewis:

Your request for information on the 1/4 corner between S 31, T 26S -R 7W and S.6 T 27S -R 7W has been referred to me by Lyle Boustead of our Springfield Branch. I have made inquiries regarding work done in the area. I understand that Mr. John Ohman was doing some corner recovery work in that area in 1952 and quite possibly was involved in work in the area in question. Unfortunately Ohman has left the Company, and we have no record of his notes concerning the corner.

Yours very truly,

WEYERHAEUSER COMPANY

*Jack Palmquest*  
Jack Palmquest  
Branch Forest Engineer

JP/mg  
cc: H. Henderson  
file

FILED  
RECEIVED

MAR 30 1966

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

C.S. 54/23-1