

56 | 55
Renew Sec. Cor. 57 | 58 T265 R7W

Fd. BT's as follows -

Orig. 16" Now 25" ^{FIR} S. 85° E. 11 7/8 ft. (face)

We open & find "SB" scribe & Reverse.

Orig. 24" Now 36" FIR (STUMP) S. 80° W. 9 3/4 ft (face)

No scribe fd. OR NE. BT. is shattered STUMP
out of place & N.W. is SNZG showing faint

scar. also find UNRECORDED BT's follows

18" D. FIR S. 65° E. 35 1/4 ft.

Mkd. " T26 R7 SB BT RE 2741 "

Set 1" I.P. & BRASS CAP MKD. " COUNTY SURVEYOR'S

OFFICE 1966 T265 ^{56 | 55} 57 | 58 R7W " & MARK

New BT's -

11" chinquapin N. 64° W. 54 3/4 ft.

Mkd. " T265 R7W 56 CS BT "

5" D. FIR N. 14° E. 34 3/4 ft.

Mkd. " S 5 CS BT "

4" D. FIR S. 27° W. 11 6/8 ft.

Mkd. " S 7 CS BT "

This cor. lies in very brushy

old logged off unit.

May 31, 1966

V.R.P.
M.S.
J.H.

76 O.K. J.W.B.

C.S. File No. 54/23-21