

Renew Wit. COR. to $\frac{1}{4}$ 534 } 535 T265 R7W

Fd. 2" I.P. 6" below surface of ground.

& B.T. as follows -

Orig. 12" Now 26" W. 00K. S. 16° E. 171 $\frac{1}{2}$ Ft.

We open & find very faint Reverse
scribe & axe notch. We find no trace

of B.T.s Recorded in Renewal # 18 or

other Orig. B.T. - actual cor. falls in

Road. - I.P. is 20° Ft. East of cor. we

set 1" I.P. & Brass cap alongside I.P.

FOR WIT. COR. MKD. " COUNTY SURVEYOR'S
OFFICE. 1966 T265 WIT. COR. $\frac{1}{4}$ 534 } 535

20 FT. WEST TO COR. R7W" & MK

New B.T's -

13" W. 02K. N. 1° E. 134 $\frac{1}{2}$ Ft.

MKD. " W.C. $\frac{1}{4}$ 535 CS BT "

9" W. 02K.S. 28° E. 39° Ft.

MKD. " W.C. $\frac{1}{4}$ 535 CS BT "

No Trees available to West of Line.

Witness Cor. falls in N-S. fence

ON East side of Road course N. & S.

635 $\frac{1}{2}$ Ft. N. of fence cor. fences

N.-S. & N.E.

March 30, 1966

[Handwritten Signature]

U.R.T.
M.S.
J.H.

O.V. J.B. C.S. File No. 54/23-25