

35 | 36 T255 R7W Wit. COR.  
Renew Sec. 2 | 1 T275 R7W Wit. COR.

Fd. BT. 25 Recorded in Ren. # 26 & I.P.'s used

25 References as follows -

12" Now 24" D. Fir S.  $40^{\circ}$  W 81 $\frac{0}{2}$  ft.

Recorded as W. Fir - we chop out BT.

1" I.P. N.  $58^{\circ}$  E. 26 $\frac{8}{2}$  ft.

1" I.P. S.  $51^{\circ}$  E. 29 $\frac{0}{2}$  ft.

We do not I.P. set for COR. OR I.P. T.M.W.

COR. Falls in Road. We set Witness

CORNER 23 $\frac{0}{2}$  ft. East of True COR. - set

1" I.P. & Brass Cap MKd. "COUNTY SURVEYOR'S

OFFICE 1966 T265 Wit. COR.  $\frac{535}{52}$  |  $\frac{536}{51}$

R7W 23 FT. W. TO COR. T275" & MK. New

BT's -

8" cedar N.  $42^{\circ}$  W. 56 $\frac{0}{2}$  ft.

Mkd. "WC T265 R7W 535 CS BT"

9" cedar S.  $65^{\circ}$  W. 48 $\frac{2}{2}$  ft.

Mkd. "W.C. T275 R7W 52 CS BT"

No Trees close to East - we use old

Reference I.P.'s as follows -

1" I.P. N.  $1^{\circ}$  W. 13 $\frac{8}{2}$  ft.

1" I.P. S.  $2^{\circ}$  W. 14 $\frac{6}{2}$  ft.

Wit. COR. Lies on E. edge of Road course

N. & S. in old N.-S. fence

March 31, 1966

V. R. T.

M. S.

C. S. R. W. H.

AK. J. B.

54/23-27