

515/514
Renew Sec. Cor. 520/525 T275 R7W

Fd. 1754 C.S. BRASS cap in place
& B.T.S as follows - see Rev. # 52 -

10" Now 14" FIR N. 85° E. 31° ft.

Recently sawed Down - shows scar.

10" Now 10" FIR S. 24° E. 32³/₄ ft.

sawed stump - Record. 33³/₄ ft. - "BT"
scribe visible on unhealed blaze.

8" Now 13" FIR N. 42° W. 25° ft.

Now Down - shows scar.

10" Now 10" FIR S. 72° 30' W. 46⁶/₈ ft.

Now sawed stump - scribe visible on unhealed

blaze - we mk. new B.T.S -

7" D. FIR N. 30° E 31⁸/₈ ft.

Mkd. T275 R7W 514 CS BT"

10" D. FIR N. 62° W. 22⁶/₈ ft.

Mkd. T275 R7W 515 CS BT"

8" D. FIR. S. 32° W. 35⁹/₈ ft.

Mkd. T275 R7W 522 CS BT"

9" D. FIR S. 11° E. 28⁵/₈ ft.

Mkd. T275 R7W 523 CS BT"

This cor. lies on gentle

west-erly slope approx 200 ft
west of Power Line Road.

Sept 18, 1968

#158 R. T. Truitt
C.S. File No. 54/256-28

U.R.T.
J.H.

O.K.
J.W.B.