

Renewal #81

2/10  
16/15

T275 R7W

Found:

- 15" W. Oak now 19" N20E 55<sup>+</sup>  
shows good scar
- (1960) 21" D. Fir now 23" N54W 82<sup>6</sup>  
shows good scar
- 15" D. Fir now 18" S61E 125<sup>E</sup>  
shows good scar

Also Brass cap at Sec cor - This cor  
to fall in Bd Duc to new corit.

Order 1

I Remove Brass cap and Reset for  
N.T. Cor M.P.

county Surveyors office

T275 R7W

59 S10  
516 S15

W.C. 25 Ft. South

To

1969

Bearing Trees

Reblaze & Rescribe

- 27" W. Oak N 91<sup>1</sup>/<sub>2</sub> E 33<sup>3</sup>/<sub>4</sub>  
scribed W.C. T275 R7W S10 25 87
- 23" D. Fir N 71 W 69<sup>7</sup>/<sub>8</sub>  
scribed W.C. T275 R7W 59 45 87
- 18" D. Fir S 53 E 120<sup>E</sup>  
scribed W.C. T275 R7W S16 25 87
- 5<sup>1</sup>/<sub>8</sub>" B/W P. O. S 57 E 18<sup>E</sup>  
STR 217+00

12-9-69

*[Handwritten signature]*

#160

O.H. J.W. 10.

C.S. File No. 54/23-801

DIETZGEN NO. 385-6