

Renewal

515/514

7313 P5W

Found:
orig stone + 1/4" Iron Pipe at
7 cor,

12" Yew NW 13" S33E 24 1/2"
Scribe visible "1/2 514 BT"

18" Fir NW 20" N71W 23 1/2"
Shows good scar,

12" Yew is on edge of cut Bank
and the appearance of tree is bad

New Bearing Tree:

7" D. Fir S59E 11 1/2"
Scribed 1/2 514 55 BT

Renewal # 24

5-12-66

~~2210~~
~~2210~~
~~2210~~

* 75

C. S. File No. 54/25-5

DIETZEN NO. 385-6