

Renewal

$\frac{29}{32}$

7315 R5W

Found:

2-1 $\frac{1}{2}$ " Iron Rods at f cor:

24" Fir NW 15 $^{\circ}$ E

This tree had old axe mark
and location tag, but no
scribe marks.

24" Fir NW 35 $^{\circ}$ E

Not Found.

This tree lies inside
gas line boundary.

New Bearing Trees:

3" Fir N78W 11 $^{\circ}$

Scribed $\frac{1}{2}$ 529 65 BT

3" Fir S21W 20 $^{\circ}$

Scribed $\frac{1}{2}$ 592 13T

Power Line Rd bears

East 100 $^{\circ}$

Gas line bears West 30 $^{\circ}$

Renewal $\frac{1}{2}$

[Handwritten signature]
J. C. B.

Ox77

C.S. No. 57/25-7

DIETZGEN NO. 385-6