

Renewal

$\frac{324}{525}$

T31S R5W

Found No Trace of Laurel Tree  
15" D. Fir Now Stump N23E 48°

Back scribed. Not all there  
curved part of B and T

Also FD. Set stone at car No  
Markings visible  
Approx. Record Size

Renewed!

Set Brass cap at  $\frac{1}{4}$  car MTR.  
County Surveyors Office

T31S R5W

$\frac{1}{4}$   $\frac{524}{525}$

1966

New Bearing Trees

23" D. Fir N43E 20°

Scribed  $\frac{1}{4}$  S 29 c.s. BT

7" Cedar S38W 32°

Scribed  $\frac{1}{4}$  S 25 c.s. BT

This car lies on East slope  
about 140° From Top of Ridge

6-17-66

~~W.M.~~  
~~W.M.~~  
T.C.

\*OK J.W.B.

C.S. No. 54/25-10

DIETZGEN NO. 385-6