

Renewal

533/334

T.31S R5W

Found:

1/2 Iron Pipe at cor.

40" Fir S 67 W 41 E  
Blows down

26" Fir Now 38" S 56 E 31 Z

Both Scribes visible "1/4" "7"

Renewed:

Along side Iron Pipe  
Set of Brass cap M.H.D. (at cor.)

county surveyors office

T.31S R5W

1/4 533 534

1966

New Bearing Trees:

9" Maple S 44 W 22 L  
Scribed 1/4 533 CS BT

9" Live Oak N 48 E 39 E  
Scribed 1/4 534 CS BT

6-22-66

J.P.P.  
T.M.P.  
T.C.C.

#97/

\* ON J.W.B. C.S. File No. 54/25-11