

Revised 327/526 T315 R5W

Found:

14" D. Fir Now 29' S75W 29Z  
Tree Dead  
Very Faint Part Scribe "S"  
and other Marks not legible

15" Fir N70E 13Z  
No trace of this tree.

Revised:

Set Brass cap at  $\frac{1}{4}$  sec corner

County Surveyors office

T315 R5W

$\frac{1}{4}$  S27/526

1966

DIETZGEN NO. 385-6

New Bearing Trees:

10" D. Fir N69E W 5Z  
Scribed  $\frac{1}{4}$  S 27 CS BT

12" Yew N32 E 35Z  
Scribed  $\frac{1}{4}$  S 26 CS BT

This cor lies South of Edge  
90<sup>o</sup> Ft.

5-31-66

#89 O

O.K.

J.W.B. C.S. File No. 4/25-47

*[Handwritten signature]*