

Renewal

58 | 59  
517 | 516

T315 R5W

Found:

1" Iron P. R. at Sec cor.

48" Fir Now 28" N29W 59<sup>5</sup>  
Bark scribed T315 R5W SB CS BT

18" Fir Now 21" S64<sup>1</sup>/<sub>2</sub>E 86<sup>5</sup>

12" W. Fir Now 11" S 91<sup>1</sup>/<sub>2</sub>W 10<sup>2</sup>

24" W. Fir Now 24" N69<sup>1</sup>/<sub>2</sub>E 8<sup>7</sup>  
Face Bottom on this tree.

6" Dogwood Now dead S21E 7<sup>2</sup>  
This is OBT

All Trees have recently been opened  
but at. with the exception of one.

New Bearing Tree.

28" D. Fir N86E 56<sup>2</sup>  
scribed. T315 R5W S9 CS BT

Reblazed + Rescribed:

48" Fir N29W 39<sup>5</sup>  
scribed. T315 R5W SB CS BT

Cor Now lies in cutting cor.

Renewal #36

5-23-66

J. M. G.  
J. W. G.  
J. C. G.

85  
⊗

D.V. J.W. G. File No. 54/25-19

DIETZGEN NO. 385-6