

Renewal

$\frac{59}{516}$

T31S R5W

Found:

14" Iron Pipe at $\frac{1}{4}$ sec cor.

12" W. Fir Now 13" N64W 41 $\frac{1}{2}$
Shows good Scar.

12" Yew Now 11" N74E 38 $\frac{5}{8}$
Scribe visible - $\frac{1}{4}$ 59 BT"

Cor Trace Stump Scribe visible
 $\frac{1}{4}$ 5"

Remarks:

Along Side Iron Pipe

Set Brass cap at $\frac{1}{4}$ sec cor MKD

County Surveyors Office

T31S R5W

$\frac{1}{4}$ $\frac{59}{516}$

1966

Logging Road Beats South
25?

All Trees in good shape

Renewal # 21 5-23-66

O.K. J.W.B.

C.S. File No. 54/25-20

DIETZGEN NO. 385-5

16
Q