

Renew Sec. Co. R. $\frac{528}{533} | \frac{527}{534}$ T285 R2W

Fd. old decayed wood post at cor. point
& O.B.T.'s as follows -

Orig. 14" Now 20" Fir N. 77° E. 16 $\frac{5}{8}$ ft.

2 live - shows good scars - we do not open.

Orig. 8" Now 10" Fir S. 44° E. 5 $\frac{7}{8}$ ft.

Now snag. - shows good scars - we do not open.

Orig. 5" Now 22" pine S. 29° W. 4 $\frac{6}{8}$ ft.

2 live - scribe marks visible in narrow
unhealed portion of upper scar. we

Rescribe "T285 R2W S33 CS BT"

Orig. 12" Now 16" Fir N. 20° W. 7 $\frac{3}{8}$ ft.

2 live shows good scars - we do not open.

at cor. point set 1" I.P. & Brass cap

Mkd. "COUNTY SURVEYOR'S OFFICE

1968 T285 $\frac{528}{533} | \frac{527}{534}$ R2W" & MARK

New B.T. -

8" cedar S. 53° E. 16 $\frac{3}{8}$ ft.

Mkd. "T285 R2W S34 CS BT"

This cor. lies on moderate E.

slope.

July 11, 1968

V.R.T.
J.H.

V.R.T. Tray

47 O.K. J.W. C.S. File No. 57/26-11