

Renew $\frac{1}{4}$ 527/526 T255 R3W

Fd. G.L.O. BRASS CAP MKd. $\frac{1}{4}$ 527/526 1943"

\$ 1743 Resurvey BT's as follows -

50" Now 53" Fir South 35 $\frac{1}{2}$ ft.

Shows good scar - we do not open - 2 live.

50" Now 55" Fir S. 60 $\frac{1}{2}$ ° W. 104 $\frac{1}{2}$ ft.

Shows good scar - we do not open - 2 live

Orig. 1883 Hemlock S. 85° E. 44 $\frac{1}{2}$ ft.

Now Shattered STump - no scribe for

we MK. New BT's -

9" Hemlock S. 54° W. 27 $\frac{1}{2}$ ft.

Mkd. $\frac{1}{4}$ S 27 CS BT"

10" R. Cedar N. 48° E. 32 $\frac{1}{2}$ ft.

Mkd. $\frac{1}{4}$ S 26 CS BT"

Section Line is well Blazed

N. & S.

June 29, 1966

U.R.T.

J.B.

J.H.

FILED

RECEIVED

JUN 29 1966

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

✓ 251

O.K. J.W.B.

*

C.S. No.

27-10