

520 521

Review Sec. Cor. 529/528 T255 R3W

Fd. G.L.O. Brass Cap MKd. "T255 R3W

520 | 521

527 | 528 1943" All BTs as Recorded in

1943 Resurvey notes are gone, down or  
stumps - badly burned and rotted - No scribe  
marks fd. Cor. Lies approx 100 ft. North

of Cor. of Timber in Dense Reproduction  
of D. Fir & Hemlock. we MK. New BTs -

3" Hemlock N. 42 °W. 3<sup>5</sup> ft.

Mkd. "520 CS BT"

4" D. Fir S. 74 °W. 6<sup>0</sup> ft.

Mkd. "529 CS BT"

4" Hemlock S. 9<sup>1</sup>/<sub>2</sub> °E. 25<sup>5</sup> ft.

Mkd. "528 CS BT"

4" D. Fir N. 34 °E. 25<sup>4</sup> ft.

Mkd. "521 CS BT"

also steel fence post set along  
side Brass Cap.

July 11, 1966

FILED

V.R.T.

J.H.

RECEIVED

JUL 11 1966

*[Signature]*

COUNTY SURVEYOR  
DOUGLAS COUNTY, ORE.

\*#72

O.R. J.W.B.

C.S. File No. 54/27-28