

Renew $\frac{1}{4}$ $\frac{59}{516}$ T255 R3W

Fd. G.L.D. BRASS Cap MKd. $\frac{1}{4}$ $\frac{59}{516}$

1744" with steel Fence post along
side & 1744 Resurvey B.T.'s as follows -

8" Now 16" D. FIR N. 10° E. 17 $\frac{3}{4}$ FT.

previously opened & shows "B"
scribe. alive

12" Now 21" W. FIR S. 42° W. 41 $\frac{1}{2}$ FT.

Fragmentary scribe visible on badly

Injured Blotz. We MK. New B.T.'s

8" R. cedar N. 22° E. 9 $\frac{2}{4}$ FT.

Mkd. $\frac{1}{4}$ 59 CS BT "

7" D. FIR S. 15° E. 16 $\frac{1}{4}$ FT.

Mkd. $\frac{1}{4}$ 516 CS BT "

BRASS Cap Lies Between Two

Rotted Logs in young Fir &

Hemlock Timber.

August 4, 1966

V.R.T.
J.B.
J.H.

FILED

RECEIVED

V.R.T. Ray

AUG 4 1966

COUNTY SURVEYOR

DOUGLAS COUNTY, ORE.

189
X

Oik. J.W.B.

C.S. 54/27-50