

Renew $\frac{1}{4}$ $\frac{515}{522}$ T255 R3W

Fd. G.L.O. BRASS Cap MKd. " $\frac{1}{4}$ $\frac{515}{522}$ 1943"

with Steel Fence post set along side.

Both orig. BTs are down & out of place. scribe mk. visible on SW BT.

1943 BT gone completely, we MK new BTs -

5" D. FIR S, 31° E, 16² FT, MKd. " $\frac{1}{4}$ 522 CS BT"

5" cedar S, 71 $\frac{1}{2}$ ° W, 31¹ FT, MKd. " $\frac{1}{4}$ 522 CS BT"

8" D. FIR N, 47° W, 42⁴ FT, MKd. " $\frac{1}{4}$ 515 CS BT"

This cor. lies on S.W. slope 1 chain East of small creek cours N. 15° W.

August 31, 1966

V.R.T.
J.B.
J.H.

(Handwritten signature)

FILED
RECEIVED

AUG 31 1966

COUNTY SURVEYOR
DOUGLAS COUNTY, ORE.

* $\frac{515}{522}$ ○

C.S. File No. 54/27-168